Sistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0917

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Phone: (731) 989-5111

Fax:

Email Address:

Agency Contact: Murley, Rickey

Work Phone: Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-736-0163

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Alt. Client ID: 16016SW-0917

Work Order Name:

Report Run On: 5/14/2010

Page 1 of 5

Measures

	Measure 1 Infiltr	ation Redctn			Componen	ts			Inspected
C	omment				er er er er	Actual			
			1114	O4	Estimated Unit Cost	Total	Qty	Unit Cost	Total
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	TOLAT	Qty		7,014.
1	Construction Materials/Hardwar e	Seal pipes under all sinks and vanities, Repair ceiling in front bedroom	Each	1		***************************************		arman and a second a second and	
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal behind washer and dryer, Seal off attic doors 1 front bath 1 from the hall,	Each	1			TOTAL PROPERTY OF THE PROPERTY		
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal off furnace vents, Seal ceioling in front bedroom approx area 8x5	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Seal door off to basement, Seal AC in middle bedroom, Repair kitchen ceiling approx area 5x6	Each	1	Francisco				
8	Labor	Labor	Hour		1 mm. mm.				
9	Construction Materials/Hardwar e	Caulk and glaze all windows as needed qnty 38	Each	1			Parlamente		
10	Labor	Labor	Hour						
(Other Detail			7 /					
		AAA WAXAA AAA AAAA AAAA AAAA AAAA AAAA						1	
				Measu	re Sub Total:			Sub Total:	
	Field Notes:								

Client Name:

Client ID:

Alt. Client ID: 16016SW-0917

Work Order (Bid Form)

Work Order Name

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 5

Measure 2 DWF Comment	l Pipe Insulation			Componen	ts		li	nspecte
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail							·	***************************************
								MANAGEMENT OF THE STATE OF THE
		,	Measur	e Sub Total:			Sub Total:	
1								
	L D 20			Componen	έο Λ1		I	nsnecte
	Ins. R-30			Componen	ts A1		I.	nspecte
	Ins. R-30			Componen Estimated			l. Actual	nspecte
Comment	Ins. R-30 Description / Comment	Units	Qty	·		Qty		nspecte
Comment Material / Labor		<i>Units</i> SqFt		Estimated		Qty	Actual	
Comment Material / Labor Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated		Qty	Actual	
Comment Material / Labor Insulation Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30	SqFt	Qty 540	Estimated		Qty	Actual	
Material / Labor Insulation Labor Construction Materials/Hardwar e	Description / Comment Attic Insulation - Blown Cellulose - R-30 Labor	SqFt Hour	Qty 540	Estimated		Qty	Actual	
* Material / Labor Insulation Labor Construction Materials/Hardwar e Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Labor Install attic access cover	SqFt Hour Each	Qty 540	Estimated		Qty	Actual	
* Material / Labor Insulation Labor Construction Materials/Hardwar e Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Labor Install attic access cover	SqFt Hour Each	Qty 540	Estimated		Qty	Actual	
* Material / Labor Insulation Labor Construction Materials/Hardwar	Description / Comment Attic Insulation - Blown Cellulose - R-30 Labor Install attic access cover	SqFt Hour Each	Qty 540	Estimated		Qty	Actual	

Client Name:

Client ID: ____ Alt. Client ID: 16016SW-0917 Work Order (Bid Form)

Work Order Name Report Run On: 5/14/2010 DOE Weatherization Assistant Version 8.5.0

Page 3 of 5

ł Tank Insulation			Componen	ts			Inspecte
			Estimated				
Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
DHW Tank Insulation	Each	1					
Labor	Each	1					
	No. ob harmon of any years and a state of the state of th	Measur	e Sub Total:]	Sub Total:	
Monitor is Needed			Componen	ts			Inspecte
			•				
			Estimated			Actual	
Description / Comment	Units	Qty	·		Qty		Total
Description / Comment CO monitor	<i>Units</i> Each	<i>Qty</i> 1	Estimated		Qty	Actual	
			Estimated		Qty	Actual	
CO monitor	Each	1	Estimated		Qty	Actual	
CO monitor	Each	1	Estimated		Qty	Actual	
CO monitor	Each	1	Estimated		Qty	Actual	
CO monitor	Hour	1	Estimated			Actual	
CO monitor	Hour	1	Estimated Unit Cost			Actual Unit Cost	
CO monitor	Hour	1	Estimated Unit Cost			Actual Unit Cost	
Management Springers Street	Description / Comment DHW Tank Insulation Labor	Description / Comment Units DHW Tank Insulation Each Labor Each	Description / Comment Units Qty DHW Tank Insulation Each 1 Labor Each 1 Measure	Description / Comment Units Qty Unit Cost DHW Tank Insulation Each 1 Labor Each 1 Measure Sub Total:	Description / Comment Units Qty Unit Cost Total DHW Tank Insulation Each 1 Labor Each 1 Measure Sub Total:	Description / Comment Units Qty Unit Cost Total Qty DHW Tank Insulation Each 1	Description / Comment Units Qty Unit Cost Total Qty Unit Cost DHW Tank Insulation Each 1

Client Name: Client ID:

Alt. Client ID: 16016SW-0917

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/14/2010

1

DOE Weatherization Assistant

Version 8.5.0 Page 4 of 5

Measure 6 Fix	Any Other Heating Syste	em Probl	em	Componen	ts		I.	nspected
Comment Remov	e all non-vented heater th	at do not l	have a	oxygen dep Estimated	letion se	nsor	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Direct Vent 35-40 KBTU Natural gas Heater	Each	1			1		
2 Labor	Labor	Hour	1					
Other Detail				****	· · · · · · · · · · · · · · · · · · ·] []		
] []] []		
			Measur	e Sub Total:			Sub Total:	
Field Notes:							-	
Measure 8 Sm	oke Detector is Needed	V-2		Component				nspected
	5	11		Estimated	~		Actual Unit Cost	Total
# Material / Labor1 Health and Safety Items	Description / Comment Smoke detector	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty		TOTAL
2 Labor	Labor	Hour	1					
Other Detail						7		
] []		
			Measur	e Sub Total:			Sub Total:	1
Field Notes:								
L		Mort O	dor Cr-	nd Total:		Gran	d Total:	
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name:

Client ID: Alt. Client ID: 16016SW-0917 Work Order (Bid Form)

Work Order Name

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 5